


5. Route the AirPort antenna cable up through the opening in the internal frame.



6. Check that the power button cable is not pinched by the internal frame.

